

# ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE ER REGULATORY CONTACT RECORD

**Date/Time** April 8, 2004/ 0815

**Site Contact(s)** Annette Primrose  
**Phone** 303 966-4385

**Regulatory Contact** David Kruchek  
**Phone** 303 692-3328

**Agency.** CDPHE

**Purpose of Contact** Transformer Pads at B991/PAC 900-1306

## **Discussion**

There are two transformer pads located east of B991 in an area of five small slabs. Six samples were collected at this location immediately adjacent to the slabs and were biased to the areas with the highest potential for contamination including stained areas. The highest PCB concentration was Aroclor 1260 at 510 ppb which is an action level of 12,400 ppb.

Based on this, it was agreed that no action is required at this site and the slabs can be pulled.

**Contact Record Prepared By** Gerry Kelly

## Required Distribution


S Bell, RFFO  
L Brooks, K-H ESS  
L Butler, K-H RISS  
C Deck, K-H Legal  
S Gunderson, CDPHE  
J Legare, RFFO  
L Norland, K-H RISS

D Mayo, K-H RISS  
J Mead, K-H ESS  
S Nesta, K-H RISS  
K North, K-H ESS  
D Shelton, K-H  
C Spreng, CDPHE

## Additional Distribution

(choose names as applicable)

M Broussard, K-H RISS  
J Hindman, CDPHE  
G Kleeman, USEPA  
D Kruchek, CDPHE  
A Primrose, K-H RISS  
E Pottorff, CDPHE



ADMIN RECORD

LA-A-002061